

F377

AC - SOUR CIP CLEANER NF

This product is a concentrated non-foaming acid based cleaner designed for use in dairy plants. It is formulated for *in-place* cleaning of farm pipelines, bulk tanks, and automatic milking systems.

DIRECTIONS:

Pre-flush with cold potable water to remove any residual milk products in the system. Then wash well with a high pH C.I.P. cleaning solution; this will remove all remaining milk and butterfat from the surface of pipes and tanks. Rinse well with warm water to remove all detergent from the system.

Make a solution of acid cleaner using 0.5% (5ml/L) *AC - Sour CIP Cleaner NF* diluted with warm (70-80°C) water and circulate for 10 minutes. Thorough draining and rinsing with potable water must be done after acid cleaning. For heavier buildup, a higher concentration of acid solution may be required.

COMMERCIAL USE ONLY

January 14, 2020



Intertek